

Structural Sign-Off Review

Project: Solar Panel Installation

Project No. xxx-xxx

Location: 123 Sample St

Date: xx-xx-xxxx

Client: Sample Client Name

Application #

Reported by: Leekor Staff

Distribution: xxx

Further to our review of the installation of the racking and solar panels, it is confirmed that the work has been completed in accordance with the structural drawings as stamped by Leekor Engineering, and is considered to be acceptable.

Photograph 1

- Racking and solar panels have been installed on all roof areas as per plans, including the repositioning of some panels.



Photograph 2

- View of completed installation of PV array.



Photograph 3

- View of panel mounted to wall in the basement.



Should you have any questions regarding this report please contact the undersigned.

LEEKOR Engineering Inc.,

Leekor Staff

Signature here

Stamp here